





Part Number	K10003	Box Part Number BX21 Dimension 30.25 x 8 x 5
Description	Saddle	Other Packaging
		Logo Decals
Packaging Instructions and Decal Placement		
K10003  Place previously foamed saddles in box then add hardware. Place some foam on the top to prevent hardware from moving. Seal box and apply label D2927-3 as per instructions in QSI 014 section 4.5.  NOTE: Fill all voids of box with foam to prevent movement.		

D2729-4

N/A

D2729-3

DAS 16 9-89 2018/11/52



Dart Aerospace Ltd. 1270 Aberdeen Street Hawkesbury, ON K6A 1K7 CANADA TEL.: 1 613 632-5200

## K10003 SADDLE

## **INCLUDE PARTS FOR:**

D205-634-011 D205-634-015

D204-635-011 D204-635-111

D205-634-111

S/N: SXXXXXX

Revision: N

Date: 18.11.26